



**LAA TYPE ACCEPTANCE DATA SHEET**  
**TADS 301A**  
**DYN AERO MCR-01 CLUB**

Issue 5	Changes to manufacturer's/importer's details. New format. Addition of MPD 2011-002-E. Addition of MOD/301/021, /022 and /023. Manufacturer's service information updated.	Dated 19/07/16	JV
---------	---	----------------	----

These TADS are intended as a summary of available information about the type and should be used during the build, operation and permit revalidation phases to help owners and inspectors. Although it is hoped that this document is as complete as possible, other sources may contain more up to date information, e.g. the manufacturer's website.

Section 1 contains general information about the type.

Section 2 contains information about the type that is **MANDATORY** and must be complied with.

Section 3 contains advisory information that owners and inspectors should review to help them maintain the aircraft in an airworthy condition. If due consideration and circumstances suggest that compliance with the requirements in this section can safely be deferred, is not required or not applicable, then this is a permitted judgement call. This section also provides a useful repository for advisory information gathered through defect reports and experience.

**Section 1 – Introduction**

1.1 UK contact

| There is no UK importer at the current time.

1.2 Description

The MCR01 series is a single-engined two-seat monoplane design of composite construction, developed from the Colomban Ban-bi design, both designs having been developed in France. The Dyn-Aero MCR-01 Club variant of the aircraft is fitted with wings and tailplane of greater area and a different wing section to that of the original MCR-01 VLA variant and separate flaps and ailerons rather than combined flaperons. The Club variant was developed by Dyn-Aero as a less demanding to fly variant for less experienced pilots.

The fuselage is a two-part moulding, split horizontally, with a fin skin moulded integral with the upper fuselage half and the firewall integral with the lower half. A fuel tank is fitted between the instrument panel and the firewall. A one-piece canopy is fitted over the cockpit, hinged at the front, allowing straight-forward access to the side-by-side seating arrangement. The horizontal tail is in a T-tail arrangement on top of the fin, and is a one-piece all-flying surface, fitted with a trailing edge anti-balance tab. The wing is in two pieces and the wing panels are easily deriggable from the fuselage using a glider-style overlapping spar-tang design. The wing panels are fitted with large-span double-slotted flaps, and ailerons. This aircraft is fitted with a quick-disconnect on the flap operation system which allows the aircraft to be easily rigged and de-rigged without the need for independent inspection.

The fuselage shell halves are manufactured from a multi-axial stitched carbon-fibre cloth and are moulded with an epoxy resin using the wet lay-up technique, vacuum bagged during cure for consolidation. Unidirectional carbon fibre stiffeners are used at the bottom and the top of the lower hull. These stiffeners form the longerons of the



**LAA TYPE ACCEPTANCE DATA SHEET**  
**TADS 301A**  
**DYN AERO MCR-01 CLUB**

fuselage. The fuselage frames carrying undercarriage and wing attachments are manufactured from wood with carbon fibre faceplates. All other fuselage frames are +/-45 degree carbon/epoxy/foam sandwich construction. Each wing panel has a box spar manufactured with +/- 45 degree carbon fibre shear webs and pultruded carbon-fibre/epoxy spar caps of variable thickness, the whole assembly being epoxy-bonded together under pressure. The root-rib of the wing is manufactured from stamp-moulded woven carbon-fibre/epoxy, while the remaining ribs are from 6mm thick PVC foam, close pitched to provide support against wrinkling for the one-piece sheet aluminium skins. The tailplane has a similar construction to the wings, although the skins are available manufactured from either woven carbon fibre or sheet aluminium. Either design of skin is acceptable. Carbon-fibre ribs are used at the centre of the tailplane to react torque loads into the control rod.

The vertical tail has upper and lower ribs manufactured from carbon-fibre, while the intermediate ribs are from PVC foam. The rear spar of the fin is manufactured from UD carbon caps with a +/-45 degree carbon-fibre shear-web. The rudder, flaps and ailerons are manufactured from a one-piece wrap-around aluminium skin with a PVC foam spar and carbon fibre ribs at point load attachments, with PVC foam intermediate ribs. The aluminium skin is bonded and riveted at the trailing edge. Woven carbon fibre skins are an acceptable factory option.

The main undercarriage is a fixed tricycle type with a one-piece carbon-fibre/glass/epoxy cantilever spring, while the noseleg is made up of telescopic steel tube.

The engine type accepted by the LAA on the Club is the Rotax 912-ULS, normally with a ground adjustable Ecoprop 160R130/3 propeller (set at a pitch angle of 27 degrees measured at 75% radius) or variable pitch Arplast PV50 160R130/3 or MT Variable Pitch Propeller MTV-7-A/156-122.

Note that the only propeller(s) approved for an individual aircraft are those listed on the individual aircraft's Operating Limitations document or in the PTL/1 (Propeller Type List) for the type.

The MCR-01 Club is an SEP ('Group A') aircraft.

## **Section 2 – Mandatory information for owners, operators and inspectors**

At all times, responsibility for the maintenance and airworthiness of an aircraft rests with the owner. Condition No 3 of a Permit to Fly requires that: *"the aircraft shall be maintained in an airworthy condition"*.

### **2.1 Fast Build Kit 51% Compliance**

The LAA technical leaflet TL.11 shows the contents of the accepted fast build kit.

### **2.2 Build Manual**

The build manual is provided on a CD supplied by the manufacturer with the kit, ref: MEXNO02.



LAA TYPE ACCEPTANCE DATA SHEET  
TADS 301A  
DYN AERO MCR-01 CLUB

2.3 Build Inspections

Build inspection schedule 34 (Dyn Aero MCR 01).

Inspector approval codes A-A or AC-1 or K. Inspector signing off final inspection also requires 'first flight' endorsement.

2.4 Flight Manual

Flight Manual ref: OEXNO07.

2.5 Mandatory Permit Directives

Applicable specifically to this aircraft type:

<a href="#">1999-013</a>	Elevator trim tab control	This MPD refers to DGAC AD 1999-385 which in turn refers to Dyn-Aero Bulletin Service <a href="#">BS 20 1 0001</a> . This requires removal of the tailplane and removal of the rod lower attachment to perform inspection of the rivets attaching the rod ends to the control rod. There should be no play. This inspection is required every 50 hours.
<a href="#">2005-013</a>	Replacement Baumeister flap servo motor	With effect from 31/12/05, use of the Baumeister flap drive motor fitted with the John Scott flap operating system is not permitted. An alternative, approved by the LAA, must be installed. LAA letter to owners Mr Bishop, Greenwood and Scott re mod 11744 and MPD 2005-013 Baumeister Motor refers, also LAA <a href="#">MOD/301/019</a> refers.
<a href="#">2005-014</a>	Installation of audible stall warner	With effect from 31/12/05 all LAA Dyn-Aero MCR-01 aircraft must be fitted with an audible stall warning device. See LAA <a href="#">MOD/301/018</a> .
<a href="#">2008-002</a>	Tailplane attachment failure	With effect from 8/2/08, the tailplane attachment brackets of all MCR-01 variants must be modified before further flight (LAA <a href="#">MOD/301/020</a> refers). The modification method used depends on the type of tailplane attachment brackets fitted to the aircraft.
<a href="#">2011-002-E</a>	Aluminium fittings – Inspection	With effect from 20/4/11, all LAA Dyn-Aero MCR-01 aircraft must be inspected for integrity and security of metal fittings (LAA <a href="#">MOD/301/022</a> refers).

Also check the LAA website for MPDs that are non-type specific ([TL2.22](#)).

2.6 LAA Required Modifications (including LAA issued AILs, SBs, etc)

MOD/301/001 Extra reinforcement of lap strap attachments. The seat belt attachments to the fuselage have been reinforced by laminating additional plies of carbon fibre over the aft ends of the bathtub fittings, to improve impact resistance. The seat-belt attachments to the fuselage have been reinforced by laminating additional plies of



LAA TYPE ACCEPTANCE DATA SHEET  
TADS 301A  
DYN AERO MCR-01 CLUB

	carbon fibre over the aft ends of the bathtub fittings, to improve impact resistance. Not required after Kit #130 as improvement incorporated as standard.
MOD/301/002	External door handles required. Factory optional external door handles or equivalent required to be installed. These should be easily opened from outside the aircraft without additional equipment.
MOD/301/003	Wire-lock flapperon quick-release connectors so they cannot disengage in flight.
MOD/301/004	Wire-lock the elevator anti-balance tab hinge pins, or use two M3 plain nuts locked together and Loctite adhesive.
MOD/301/005	Protect wooden cappings of wing spar tangs with varnish (or thin cope of dope followed by wax polish has been found satisfactory for ease of rigging/de-rigging). Procedure is now specified in the aircraft build manual.
MOD/301/006	Rudder horn/cable attach bolts must be retained by castle nuts and split pins rather than stiffnuts, as should any other bolts where rotation occurs around the bolt. Now factory standard.
MOD/301/007	Bolts replace blind rivets in tension for the attachment of the pitch control rod bracket to the leading edge of the tailplane. Now factory standard.
MOD/301/008	Placard seat adjustment to stress importance of proper engagement
MOD/301/009	Fit baggage compartment covers / FOD guard to prevent loose objects in cockpit jamming in flap system or rudder cables. Factory option or equivalent is mandatory. The system must be fitted between frames 4a, 4b, 5 and 6 and a guard must also be fitted to the pulley behind frame 6.
MOD/301/010	Quick release connector in pitot-static system (if fitted) to be of type acceptable to the LAA. An approved connector is available from Lyndhurst Touchdown Services, the UK kit agent.
MOD/301/011	Fuel drain must drain fuel overboard. Factory standard on all models.
MOD/301/012	Pitch trim indicator to be fitted if pilot-controllable elevator trim tab is installed. N/A to VLA Spotster model if factory standard bias spring pitch trim system fitted as provided the aircraft is correctly configured the control stick may act as the indicator, i.e. ensure that control stick neutral position is vertical prior to take-off.
MOD/301/013	Padding to be added to cockpit combing over instrument panel to provide protection from head injury in a forward impact.
MOD/301/014	Rivetting of trailing edges of controls and wing trailing edges, now factory standard ref 'Gammes de rivetage voilure et gouverne MCR-01'. Not required on carbon skinned control surfaces.
<a href="#">MOD/301/015</a>	Flap deflection reduced to 35 degrees maximum.
<a href="#">MOD/301/016</a>	Engine mount diagonal brace – new reinforced part to be fitted
<a href="#">MOD/301/017</a>	Nose Landing Gear Check (ref Dyn Aero <a href="#">BS 05 J 0027</a> )
MOD/301/017A	To avoid possibility of control restrictions in flight, ensure adequate spanwise clearance exists between aileron and flaps – minimum 3mm.
<a href="#">MOD/301/018</a>	Mandatory Stall Warning System Installation (ref Dyn Aero <a href="#">BS 05 H 0026</a> )
<a href="#">MOD/301/019</a>	Flap Drive Motors Fitted to Modified MCR01 CLUB and MCR01 ULC Aircraft.
<a href="#">MOD/301/020</a> (issue 4)	Replacement of tailplane attachment lugs
<a href="#">MOD/301/021</a>	Inspection of mainplane control surface attachment brackets.
<a href="#">MOD/301/022</a> (issue 2)	Inspection of aluminium fittings for integrity and security.



**LAA TYPE ACCEPTANCE DATA SHEET**  
**TADS 301A**  
**DYN AERO MCR-01 CLUB**

MOD/301/023 Disassembly and inspection of flapperon drive screws and carriage threads.

2.7 Additional engine operating limitations to be placarded or shown by instrument markings

Notes:

- Refer to the engine manufacturer's latest documentation for the definitive parameter values and recommended instruments.
- Where an instrument is not fitted, the limit need not be displayed.

With Rotax 912-ULS engine: Maximum CHT: 135°C  
 Max Coolant Temp: 120°C (with 50/50 Glycol/water coolant)  
 Oil Temp Limits: 50°C to 130°C (Normal 90-110°C)  
 Oil Pressure 2-5 Bar  
 Minimum Fuel Pressure: 0.15 bar

2.8 Control surface deflections

Ailerons	Up: 20° ±1° Down: 10° ±1°
Tailplane	Up: 10° +2°/-0° Down: 3.5° +1°/-0°
Elevator tab	Up and down, so as not to restrict elevator movement
Rudder	Left: 20° +0°/-2° Right: 20° +0°/-2°
Flap	Down: 35° +0°/-1°

2.9 Operating Limitations and Placards

(Note that the wording on an individual aircraft's Operating Limitations document takes precedence, if different.)

1. Maximum number of occupants authorised to be carried: Two
2. The aircraft must be operated in compliance with the following operating limitations, which shall be displayed in the cockpit by means of placards or instrument markings:
  - 2.1 Aerobatic Limitations  
Aerobatic manoeuvres are prohibited.  
Intentional spinning is prohibited.
  - 2.2 Loading Limitations  
Maximum Total Weight Authorised: 490 kg  
CG Range: 192 mm to 384 mm aft of datum point (refer to Dyn Aero weight and balance envelope)  
Datum Point is: a point 13.5 mm forward of the left wing leading edge at root (which is the mean of leading edge of port and starboard wings)



**LAA TYPE ACCEPTANCE DATA SHEET  
TADS 301A  
DYN AERO MCR-01 CLUB**

- 2.3 Engine Limitations  
Maximum Engine RPM: 5800.  
Maximum continuous engine RPM: 5500.
- 2.4 Airspeed Limitations  
Maximum Indicated Airspeed (VNE): 162 kts (300 km/h)  
Max Indicated Airspeed Flaps Extended, 0-17.5°: 89 kts (165 km/h)  
18-35°: 68 kts (125 km/h)  
Maximum Indicated Airspeed, Rough Air (VNO),  
kit #204 and after: 128 kts (238 km/h)  
kits prior to #204: 109 kts (202 km/h)
- 2.5 Other Limitations  
The aircraft shall be flown by day and under Visual Flight Rules only.  
Smoking in the aircraft is prohibited.

Additional Placards:

Cockpit placard to be fitted stating 'This is a high performance aircraft and it is recommended that pilots unfamiliar with this class of aircraft should undergo type conversion training prior to flying as pilot in command.'

"Occupant Warning – This Aircraft has not been Certificated to an International Requirement"

A fireproof identification plate must be fitted to fuselage, engraved or stamped with aircraft's registration letters.

2.10 Maximum permitted empty weight

<i>Model</i>	<i>Engine</i>	<i>Max empty weight</i>
MCR-01 Club	Rotax 912-ULS	305 kg

**Section 3 – Advice to owners, operators and inspectors**

3.1 Maintenance Manual

The manufacturers supply a maintenance manual, reference OEXNO0301.

3.2 Standard Options

- The tailplane skins and control surface skins are available manufactured from either woven carbon fibre or sheet aluminium. Either design of skin is acceptable.
- An alternative flap system option is available, designed by Mr John Scott. When fitted with this flap system, modifications are also required to the pitch trim system because the modified flap operating system displaces the normal location for the trim drive system between the seats. LAA must be consulted if this alternative flap system is planned.
- Quick release flap system connection, reference OPLPAU0.
- Hand operated hydraulic brakes.



**LAA TYPE ACCEPTANCE DATA SHEET  
TADS 301A  
DYN AERO MCR-01 CLUB**

3.3 Manufacturer's Information (including Service Bulletins, Service Letters, etc)

In the absence of any over-riding LAA classification, inspections and modifications published by the manufacturer should be satisfied according to the recommendation of the manufacturer. It is the owner's responsibility to be aware of and supply such information to their Inspector.

<i>Ref</i>	<i>Date</i>	<i>Description</i>	<i>Factory compliance status</i>
<a href="#">BS 20 I 0001</a>	14/09/99	Tab Rod	Mandatory
<a href="#">BS 20 I 0001 R1</a>	09/04/04	Tab Rod	Mandatory
<a href="#">BS 20 I 0002</a>	21/09/99	Main landing gear wheel bolts	Recommended
<a href="#">BS 20 I 0003</a>	21/09/99	Main landing gear silentblocs	Recommended
<a href="#">BS 20 I 0004</a>	21/09/99	R912 air intake security valve fixing	Mandatory
<a href="#">BS 20 I 0005</a>	21/09/99	Seat belts attachment bracket reinforcement	Mandatory
<a href="#">BS 20 B 0006</a>	14/02/00	Tailplane stiffener plate riveting check	Mandatory
<a href="#">BS 20 B 0007</a>	16/02/00	Flap control system play control	Mandatory
<a href="#">BS 20 C 0008</a>	30/03/00	JPX (BS CSB 662A) Magneto capacitors	Mandatory
<a href="#">BS 20 F 0009</a>	05/06/00	Capacitor wiring	Recommended
<a href="#">BS 21 F 0012</a>	29/06/01	Tailplane trim carriage	Mandatory
<a href="#">BS 22 I 0013</a>	07/09/01	Unleaded gasoline operation	Recommended
<a href="#">BS 22 E 0015</a>	27/05/02	Flap lead screw universal joint split pin control	Mandatory
<a href="#">BS 03 C 0017</a>	10/03/03	Main landing gear drum brake control	Mandatory
<a href="#">BS 03 K 0018</a>	12/11/03	Check of the rivet of the canopy locking system	Mandatory
<a href="#">BS 04 D 0020</a>	23/04/04	Check of adhesive tapes covering parachute straps	Mandatory
<a href="#">BS 04 F 0021</a>	14/06/04	Clearance check between wheel and main Landing gear	Mandatory
<a href="#">BS 04 F 0022 R1</a>	04/04/06	Two seater MCR main fuel tank leak	Mandatory
<a href="#">BS 04 F 0023</a>	29/06/04	Installation of flap control system	Recommended
<a href="#">SI 05 L 0003</a>	20/12/04	Ignition key-switch ACS A-510-2	[not stated]
<a href="#">BS 05 H 0026</a>	31/08/05	Stall warning system installation	Mandatory
<a href="#">BS 05 J 0027</a>	10/10/05	Front landing gear leg check	Mandatory
<a href="#">BS 06 C 0028</a>	20/03/06	Carburator air intake manifold check	Mandatory
<a href="#">BS 08 B 0034</a>	15/02/08	Elevator attachment fittings	Mandatory
<a href="#">BS 08 B 0034 R2</a>	21/05/12	Elevator attachment fittings	Mandatory
<a href="#">BS 08 D 0035</a>	10/04/08	Front landing gear leg	Mandatory
<a href="#">BS 08 D 0036</a>	21/04/08	Flight manuals update: instruction for the use of the 45° flap position	Mandatory
<a href="#">SI 09 I 0001</a>	14/09/09	Recommendations regarding the use of fuels for MCR aircraft	Information
<a href="#">BS 11 G 0001</a>	11/07/11	Inspection of pitch control surface trailing edge and stiffener bonding	Mandatory



LAA TYPE ACCEPTANCE DATA SHEET  
TADS 301A  
DYN AERO MCR-01 CLUB

<a href="#">BS 6511002</a>	29/09/11	Possibility of aileron jamming by the trim hinge	Mandatory
<a href="#">BS 13 E 0044</a>	09/04/13	Flaps control system	Mandatory

### 3.4 Special Inspection Points

- Undercarriage noseleg for signs of damage. The noseleg is rather fragile in appearance and should be checked for distortion / damage particularly following any heavy landing. (ref Dyn Aero [BS 05 J 0027](#)).
- Security of fixed noseleg lower bush. Hold down tail of aircraft to raise nosewheel off the ground, and attempt to rock the nosewheel fore and aft, looking for signs of free play.
- The flap system is unusually complicated for an aircraft in this category, consisting of electric motors, pulleys and toothed drive belts. The system needs careful attention to maintenance and inspection to preserve the integrity of the system. Any failure which causes asymmetric flap operation would cause serious control problems in flight and must therefore be avoided at all cost. The flap system requires regular inspection, see LAA [MOD/301/015](#). Particular emphasis should be placed on ensuring that owners are familiar with the special inspection requirements for the flap system.
- Problems have been experienced with failure of the very lightweight engine mount cross brace. Possibly due to engine shake during start-up and shut-down. The condition of the engine mounting cross brace must be monitored carefully in service for any signs of cracking or bending, and repaired or replaced immediately if damage is found. The Engine mount and cross brace must be painted white and flexible type coatings avoided, otherwise cracks may not be visible before a complete failure occurs.
- Owners and inspectors should remain aware of the importance of proper corrosion protection on bare metal components, and continued vigilance for its effectiveness. The principal cause of failure of the tailplane brackets in the Banbi crash referred to in MPD [2008-002](#) was identified by the AAIB as stress corrosion. The brackets were new but the AAIB (Bulletin 2/2009 G-BZXG) say there were a number of factors which may have predisposed the brackets to the onset of stress corrosion. Among one of the possible factors was poor corrosion protection. No evidence was found of any surface conversion process such as anodising having been applied to the lugs. No primer had been used and the top coat of paint was not well adhered. The manufacturer's maintenance programme for the aircraft requires a check of the security of the tailplane attachments to be performed every 50 hours and calls for the tailplane attachment lugs to be greased at 3 month intervals.

### 3.5 Special Test Flying Issues

- VP prop schedule if VP prop fitted.
- Because of the high performance of this aircraft, and the associated limitations concerning the maximum rough airspeed (VNO), pilots must be educated as to the significance of the yellow arc marking on the ASI. The majority of homebuilt aircraft are not limited by a rough airspeed. In view of this, and other high performance issues, a placard has been called for to advise pilots of the need for proper conversion training before flying an aircraft of this type.
- During flight testing it was noted that the factory pitch trim range was excessive, and a procedure has been written reference 'G-CCMM Trim Limit Setting' dated 19 January 2004 to establish satisfactory trim limits.





**LAA TYPE ACCEPTANCE DATA SHEET  
TADS 301A  
DYN AERO MCR-01 CLUB**

- On the basis of the analysis provided, LAA were not satisfied that the flap hinges are adequate for the loads on the flaps when fully deflected at the 165 km/h flap limiting speed suggested by Dyn-Aero. In order to restore adequate safety margins, the maximum permitted flap travel has been restricted to 35 degrees and the maximum permitted airspeed with flaps deflected above 17.5 degrees reduced from 165 km/h to 125 km/h.
- The first UK example G-LMLV was fitted with early style tailplane attachments which resulted in limiting the maximum speed in rough air, VNO to 202 km/hr. The first aircraft in the UK to be fitted with reinforced tailplane attachments is Dyn-Aero kit number 204. This and later aircraft have their VNO set to 128 knots (238 km/h) as quoted in the standard Dyn-Aero flight manual for the type.

----- END -----

Please report any errors or omissions to LAA Engineering: [engineering@laa.uk.com](mailto:engineering@laa.uk.com)