



**LAA TYPE ACCEPTANCE DATA SHEET
TADS P17
MT-PROPELLER**

Issue 1	Initial issue	Dated 17/03/21	JP
---------	---------------	----------------	----

This TADS is intended as a summary of available information about the propeller type and should be used during the overhaul, operation and permit revalidation phases to help owners and inspectors. Although it is hoped that this document is as complete a summary as possible, other sources contain more complete information, e.g. the manufacturer's website.

Section 1 contains general information about the propeller type and its variants.

Section 2 contains information about the propeller type that the LAA considers **mandatory** and must be complied with.

Section 3 contains advisory information that owners and inspectors should review to help them maintain the propeller in an airworthy condition. If due consideration and circumstances suggest that compliance with the requirements in this section can safely be deferred, is not required or not applicable, then this is a permitted judgement call. This section also provides a useful repository for advisory information gathered through defect reports and experience.

Section 1 Introduction

1.1 Contact Information

UK Contact: Brinkley Aerospace (Darren Carter)

Address: Unit 1
Montgomery Way
Stratton Business Par
Biggleswade
Bedfordshire
SG18 8UB

Tel: 01767 314 954
Email: info@BrinkleyAerospace.com
Website: www.brinkleyaerospace.com/propellers

UK Contact: Proptech (Ali Mant)

Address: Spitfire Way
Solent Airport
Lee-on-the-Solent
Hampshire
PO13 9FY

Tel: 023 9265 7770
Email: sales@proptech.aero
Website: www.proptech.aero

Manufacturer contact information:

Address: MT-Propeller Entwicklung GmbH
Flugplatz Str. 1
D-94348 Atting
Germany

Tel: +49 9429 4090



**LAA TYPE ACCEPTANCE DATA SHEET
TADS P17
MT-PROPELLER**

Email:
Sales: sales@mt-propeller.com
Tech support: techsupport@mt-propeller.com
Website: www.mt-propeller.com/index.htm

1.2 Description

MT-Propeller has been manufacturing propellers since 1981 and has produced in excess of 8000 examples to date including designs from motor gliders, vintage and modern types including high performance aerobatic aircraft. MT-Propeller produces a range of certificated fixed and variable pitch propellers, primarily wooden, with many of the products using a blade covering of epoxy fibreglass.

In the LAA administered fleet, MT-Propeller products have been accepted for many types from the ARV CASA 1-131E through many RVs to Pitts Specials and other aerobatic aircraft.

Section 2 Mandatory information for owners, operators and inspectors

At all times, responsibility for the maintenance and airworthiness of an aircraft (including the propeller) rests with the owner. A condition stated on a Permit to Fly requires that: "*the aircraft shall be maintained in an airworthy condition*".

2.1 Lifed Items

<i>Reference ID</i>	<i>Dated</i>	<i>Description</i>
SB 1 R5	09 Mar 20	TBO of variable pitch propellers MTV
SUPPLEMENT 1 R1 to SB 1 R5	17 Dec 20	Supplement 1 to SB 1 R5: TBO of variable pitch propellers MTV

Check the MT-Propeller website [Service Docs](#) section for updates and revisions to the above Service Bulletin and other continuing airworthiness data and maintenance information.

Also refer to LAA Technical Leaflet [TL 2.31: Low-Hours Propeller Inspection Protocol \(LPIP\)](#).

2.2 Operator's Manuals

Where possible, the manuals describing setup, operation and maintenance procedures for the propeller should be obtained from the manufacturer or importer and retained with the aircraft's records.

Check the website for MT-propeller website [Operation and Installation Manuals](#) section for free download of the relevant manual.

2.3 Maintenance Schedule

Maintenance requirements can be found in the relevant Operation and Installation Manual which can be downloaded from the [Operation and Installation Manuals](#) section of the MT-Propeller website. [Overhaul Manuals](#) are also available for download.



LAA TYPE ACCEPTANCE DATA SHEET TADS P17 MT-PROPELLER

Refer also to LAA Technical Leaflet [TL 2.31: Low-Hours Propeller Inspection Protocol \(LPIP\)](#)

Propellers fitted to LAA administered aircraft that are maintained either in accordance with the manufacturer's maintenance schedule, the CAA Light Aircraft Maintenance Schedule (LAMS) [CAP 411](#) or the LAA Generic Maintenance Schedule, further details of which can be found in LAA Technical Leaflet [TL 2.19: The LAA Generic Maintenance Schedule](#). Note: The CAA and LAA produced maintenance schedules were originally written around the maintenance requirements of aircraft fitted with traditional aircraft engines and propellers.

Some aircraft may have mandated maintenance requirements and/or schedules which are stated on the aircraft's Operating Limitations document and these must be followed.

More information on maintenance schedules can be found in the [Aircraft Maintenance](#) section of the LAA website.

Variable pitch propellers require a dedicated log book. Log books can be purchased from the [LAA Online Shop](#).

2.4 Airworthiness Directives

Certified versions may have EASA issued Airworthiness Directives which can be found via the [EASA AD Safety Publishing Tool](#).

2.5 Mandatory Permit Directives

No type-specific MPDs at this time.

Check CAA [CAP 661](#) which lists MPDs issued before 31 January 2012 and is no longer being updated.

The CAA now provides links to MPDs issued after 31 January 2012 on the [CAA MPD Listing](#) page of their website.

The LAA website should be checked for MPDs that are non-type specific in LAA Technical Leaflet [TL 2.22: Non-Type Specific MPDs](#).

2.6 CAA Mandatory Requirements for Airworthiness CAP747 and Civil Aircraft Airworthiness Information and Procedures (CAAIP) CAP562

No type specific requirements or information at this time.

CAA publications [CAP 747](#) and [CAP 562](#) contain information that may be relevant to LAA administered aircraft and should be checked for applicability.

In particular, refer to [CAP 747](#) Generic Requirement GR No. 17 which concerns the maintenance requirements for variable pitch propellers installed on aircraft holding a UK Certificate of Airworthiness but may also be pertinent to LAA administered aircraft.

2.7 LAA Required Modifications (including LAA issued AILs, SBs, etc)

No type specific required modifications at this time.



**LAA TYPE ACCEPTANCE DATA SHEET
TADS P17
MT-PROPELLER**

2.8 Operating Limitations to be Placarded or Shown by Instrument Markings

The Operating Limitations document for the aircraft will specify aircraft and powerplant limitations for that particular aircraft. Where a propeller is being fitted in accordance with a Propeller Type List ([PTL/1](#)), any limitations proscribed by the relevant [PTL/1](#) document must be adhered to.

Notes:

- Refer to the propeller manufacturer's latest documentation for the definitive parameter values and recommended placards.
- Data stated on the aircraft's Operating Limitations document must be displayed by means of cockpit placards or instrument markings.

Section 3 Advice to owners, operators and inspectors

3.1 General

Where possible, the manuals describing setup, operation and maintenance procedures for the propeller should be obtained from the manufacturer or importer and retained with the aircraft's records.

3.2 Standard Options

There are no Standard Options for any propellers fitted to LAA administered aircraft at this time.

3.3 Manufacturer's Information (including Service Bulletins, Service Letters, etc)

In the absence of any over-riding LAA classification, inspections and modifications published in the manufacturer's continuing airworthiness data should be satisfied according to the recommendations therein. It is the owner's responsibility to be aware of and supply such information to their inspector.

MT-Propellers website includes access to the following manufacturer's information:

- a. [Service Bulletins](#)
- b. [Service Letters](#)
- c. [Service Instructions](#)
- d. [Overhaul Manuals](#)
- e. [Operation and Installation Manuals](#)

3.4 Special Inspection Points

None

----- END -----

Please report any errors or omissions to LAA Engineering: engineering@laa.uk.com